




## IECEX Quality Assessment Report Summary: GB/SIR/QAR06.0030/09 details

QAR Summary :																			
QAR Reference Number *: (automatic numbering)	GB/SIR/QAR06.0030/09																		
Related QARs:	<a href="#">GB/SIR/QAR06.0030/08</a> <a href="#">GB/SIR/QAR06.0030/07</a> <a href="#">GB/SIR/QAR06.0030/06</a> <a href="#">GB/SIR/QAR06.0030/05</a> <a href="#">GB/SIR/QAR06.0030/04</a> <a href="#">GB/SIR/QAR06.0030/03</a> <a href="#">GB/SIR/QAR06.0030/02</a> <a href="#">GB/SIR/QAR06.0030/01</a> <a href="#">GB/SIR/QAR06.0030/00</a>																		
Status*:	Issued																		
QAR Free Reference Number*:	70087310																		
Audit Date*: (yyyy-mm-dd)	2018-09-06																		
Date of Issue*: (yyyy-mm-dd)	2018-11-13																		
Details of change*:	Surveillance audit and removal of Dust Ignition Protection By Enclosure Ex t																		
Valid until*: (yyyy-mm-dd)	2019-09-14																		
Site(s) audited*:	Pulsar Process Measurement Limited Cardinal Building Enigma Commercial Centre Sandy's Road Malvern Worcestershire WR14 1JJ																		
Issuing ExCB*:	SIR - SIRA Certification Service																		
Manufacturer*:	Pulsar Process Measurement Limited Cardinal Building Enigma Commercial Centre Sandy's Road Malvern Worcestershire WR14 1JJ																		
Location of Manufacture*:	United Kingdom																		
Product information*:	Ultrasonic transducers and signalling switches																		
Protection concept*:	Intrinsic Safety (ia, ib) Encapsulation (m)																		
Related IECEX Certificates: (automatic linking)																			
Related Certificates: (manual insertion)																			
Related IECEX Certificates for previous versions:																			
	<table border="0"> <thead> <tr> <th>ExCB</th> <th>CoC and Status</th> <th>Totals</th> </tr> </thead> <tbody> <tr> <td> CML</td> <td></td> <td>7</td> </tr> <tr> <td></td> <td><a href="#">IECEX CML 16.0105X issue: 0 [Current]</a></td> <td></td> </tr> <tr> <td></td> <td><a href="#">IECEX CML 16.0105X issue: 1 [Current]</a></td> <td></td> </tr> <tr> <td></td> <td><a href="#">IECEX CML 16.0106X issue: 0 [Current]</a></td> <td></td> </tr> <tr> <td></td> <td><a href="#">IECEX CML 16.0106X issue: 1 [Current]</a></td> <td></td> </tr> </tbody> </table>	ExCB	CoC and Status	Totals	 CML		7		<a href="#">IECEX CML 16.0105X issue: 0 [Current]</a>			<a href="#">IECEX CML 16.0105X issue: 1 [Current]</a>			<a href="#">IECEX CML 16.0106X issue: 0 [Current]</a>			<a href="#">IECEX CML 16.0106X issue: 1 [Current]</a>	
ExCB	CoC and Status	Totals																	
 CML		7																	
	<a href="#">IECEX CML 16.0105X issue: 0 [Current]</a>																		
	<a href="#">IECEX CML 16.0105X issue: 1 [Current]</a>																		
	<a href="#">IECEX CML 16.0106X issue: 0 [Current]</a>																		
	<a href="#">IECEX CML 16.0106X issue: 1 [Current]</a>																		

	<a href="#">IECEX CML 17.0125X issue: 0 [Current]</a>	
	<a href="#">IECEX CML 17.0125X issue: 1 [Current]</a>	
	<a href="#">IECEX CML 17.0126X issue: 0 [Current]</a>	
EMT		1
	<a href="#">IECEX EMT 18.0005X issue: 0 [Current]</a>	
SIR		3
	<a href="#">IECEX SIR 06.0025X issue: 1 [Current]</a>	
	<a href="#">IECEX SIR 18.0037X issue: 0 [Current]</a>	
	<a href="#">IECEX SIR 18.0037X issue: 1 [Current]</a>	
		11
Comment:		
Attachment:		

Last modified: 13/12/2018 17:46:08

Copyright © IEC-IECEX 2018 , Geneva, Switzerland. All rights reserved.